

CHARBAAGH

Ref: CHBG/2018-19/18AIAK/01

Date: 18.03.19

To

The principal,
Mrs. Rupa Dey,
Kalyani Public School,
Barasat-700125

Sub: - Report on Present Status of School Building from Engineering point of view


With reference to your letter No: 18AIAK/ISO/18-19, dated 15.03.19, wherein it has been stated to give a report on the present status of Kalyani Public School, Barasat-7000125, as it stands today from engineering point of view.


Under the purview of the above, the referred premises have been inspected along with representative of the school and the following observations are noted.

- 1) The referred school is a five storied building with requisite facilities, as desired.
- 2) The drawings, architectural, structural as approved by the authority have been studied and found to be in order, duly certified by the concerned engineer.
- 3) The physical condition of the building as it stands today, is in good condition and appears to be well maintained.
- 4) Fire services have been duly certified by the authority.

In general, it may be stated that the building presently noted to be sturdy, stable and fit for use from engineering point of view.

Thanking you,
Yours faithfully,


AR. SREEJATA SAHA
CA/2018/93223



Office : ~~65/57~~, Ground Floor, Sector-III, Salt Lake City, Kolkata-700 097, **IA-103**.
West Bengal, India, Tel. +91 332 358 1070

Regd. Office : 17B, Nimu Goswami Lane, Kolkata-700 005

Architectural • Interior Designing • Land Scaping • Project Management